



**Photo 3: View Looking Southwest at East End of Subject Property
and Former AST Containment Basin**



**Photo 4: View Looking West at East End of Subject Property
and Former Toluene Recovery System**



**Photo 5: View Looking West at North Side of Plant 1
(Note Overgrown Sump/Pit at Center of Photograph)**



Photo 6: Close Up of Sump/Pit on North Side of Plant 1



Photo 7: View Looking South at Drum Storage Area on West End of Plant 1



Photo 8: View Looking South at Groundwater Treatment System Storage Shed